



The STAR Pixel detector



Giacomo Contin for the STAR Collaboration Lawrence Berkeley National Laboratory

PIXEL 2016 - 8th International Workshop on Semiconductor Pixel Detectors for Particles and Imaging Sestri Levante, 5-9 September 2016





- A MAPS-based detector
- Construction
- Operations, Performance, Lessons Learned
- Conclusions



The STAR Heavy Flavor Tracker

Extend the measurement capabilities in the heavy flavor domain, good probe to QGP:

• Direct topological reconstruction of charm hadrons (e.g. $D^0 \rightarrow K \pi$, $c\tau \sim 120 \mu m$)





 $\sigma = <30 \ \mu m$

The PiXeL detector (PXL)

First vertex detector at a collider experiment based on Monolithic Active Pixel Sensor technology





PXL Design Parameters

DCA Pointing resolution	(I0 ⊕ 24 GeV/p·c) μm
Layers	Layer I at 2.8 cm radius
	Layer 2 at 8 cm radius
Pixel size	20.7 μm X 20.7 μm
Hit resolution	3.7 μm (6 μm geometric)
Position stability	5 μm rms (20 μm envelope)
Material budget first layer	$X/X_0 = 0.39\%$ (Al conductor cable)
Number of pixels	356 M
Integration time (affects pileup)	185.6 μs
Radiation environment	20 to 90 kRad / year
	2*10 ¹¹ to 10 ¹² IMeV n eq/cm ²
Rapid detector replacement	< I day

356 M pixels on ~0.16 m² of Silicon



PXL System Overview



PIXEL2016 - Sestri Levante



PXL MAPS sensor

- Ultimate-2: third MIMOSA-family sensor revision developed for PXL at IPHC, Strasbourg
- Monolithic Active Pixel Sensor technology



PIXEL2016 - Sestri Levante

9/5/2016



ionizing particle

PXL Detector Powering and Readout Chain



Construction



PXL Production, Assembly and QA



PXL Probe Testing

- Thinned and diced 50 µm-thick sensors
- Full sensor characterization
- Full speed readout (160 MHz)



- Custom made vacuum chuck
- Testing up to 18 sensors per batch (optimized for sensor handling in 9-sensor carrier boxes)
- Manual alignment (~I hr)
- LabWindows GUI for system control
- Automated interface to a database

curved thinned sensors



- Sensors built-in testing functionality
- Proper probe pin design for curved thinned sensors
- Yield 46% 60% (spare probe cards)
- Administrative control of sensor ID



Probe card with readout electronics





Sensor positioning

Ladder Assembly

Precision vacuum chuck fixtures to **position sensors by hand**

Sensors are positioned with butted edges. Acrylic adhesive prevents CTE difference based damage.

Weights taken at all assembly steps to track material and as QA. Hybrid cable with carbon fiber stiffener plate on back in position to glue on sensors.



Cable reference holes for assembly

FR-4 Handler





From ladders to sectors... to detector halves



Sector assembly fixture

Sectors

- Ladders are glued on carbon fiber sector tubes in 4 steps
- Pixel positions are measured and related to tooling balls
- After touch probe measurements, sectors are tested electrically for damage from metrology



Sector in the metrology setup

Detector half

- Sectors are mounted in dovetail slots on detector half
- Metrology is done to relate sector tooling balls to each other and to kinematic mounts

A detector half



PIXEL2016 - Sestri Levante



PXL Position Control

Sector in the metrology setup



Metrology survey

- 3D pixel positions on sector (within ~10 µm) are measured with touch probe and related to tooling balls
- Sector tooling ball positions related to kinematic mounts to relate pixel positions to final PXL location
- \rightarrow Detector-half is fully mapped



- \blacktriangleright Vibration at air cooling full flow: ~5 μm RMS
- > Stable displacement at full air flow: ~30 μm
- Stable displacement at power on: $\sim 5 \ \mu m$
- \rightarrow Global hit position resolution: ~ 6.2 μm

HFT DCA pointing resolution: (10 \oplus 24/p) μ m





PIXEL2016 - Sestri Levante

PXL Installation in STAR

Kinematic mounts



Novel insertion approach

- Inserted along rails and locked into a kinematic mount inside the support structure
- It can be replaced in < I day with a spare copy



duplicate, truncated PXL support tube with kinematic mounts





PIXEL2016 - Sestri Levante



PXL production timeline

Delivered:

- **2014 Run:** Primary Detector, 2 *aluminum cable* inner ladders, others in *copper*
- > 2015-2016 Runs: 2 detector copies, all inner ladders in *aluminum*

Sector refurbishment:

- After each STAR Run for *latch-up* induced damage
- After power supply accident during 2015 Run installation



Overall stats	#
Assembled ladders	146
Installed on sectors	127
Ladder tests	~2000

Operations, Performance, Lessons Learned



2013 Engineering Run

• PXL Engineering Run assembly crucial to deal with a number of unexpected issues







Sensor IR picture

Flawed ladder dissection: searching for shorts



- Shorts between power and gnd, or LVDS outputs
- Adhesive layer extended in both dimensions to increase the portion coming out from underneath the sensors
- Insulating solder mask added to low mass cables

- Mechanical interference in the driver boards on the existing design.
- The sector tube and inner ladder driver board have been redesigned to give a reasonable clearance fit
- ► Inner layer design modification: ~ 2.8 cm inner radius



Inner layer design

- Limited capability to remotely control power and current limits
- After the engineering run added functionality to the Mass Termination Board:
 - remote setting of LU threshold and ladder power supply voltage + current and voltage monitoring





PXL data taking



- PXL Operations
 - Hit multiplicity per sensor: up to 1000/inner-sensor, 100/outer-sensor
 - ▶ Dead time up to ~6%
 - Typical trigger rate: 0.8-1 kHz
 - Latch-up reset events: 2 latch-up/min
 - Periodic reset to clear SEUs
- Collected *minimum bias* events in the PXL acceptance:

2014 Run:	~ I.2 Bill	ion Au+Au	@ √ s_{NN} = 200GeV
2015 Run:	{ ~	ion p+p lion p+Au	@ √s _{NN} = 200GeV
2016 Run:	{ ~ 2 Bill ~ 0.3 Bil	lion Au+Au	@ √s _{NN} = 200GeV
9 G. Conti	in gcontin@lbl.gov	PIXEL2016 - Sestri Levante	9/5/2016



Operational issues: Latch-up damage



- Digital power current increase
- Sensor data corruption
- Hotspots in sensor digital section
- Correlated with *latch-up* events
- Limited with operational methods



- 50 μm & 700 μm thick, low and high resistivity sensors; PXL ladders
- Irradiation with heavy-ions and protons

Results and observations

- Current limited latch-up states observed (typically ~300 mA)
- Damage reproduced only with HI on PXL 50 μm thinned sensors

Safe operations envelope implemented

- Latch-up protection at 80 mA above operating current
- Periodic detector reset to clear SEU



Latch-up phenomenon:

- Self feeding short circuit caused by single event upset
- Can only be stopped by removing the power







Latch-up test setup and damage analysis

Individual sensor test boards and ladders mounted on cooling plate



IR "hotspots" locating the damage tend to favor particular structures (isolated buffers with specific structure pitch)





Pixel sensor layers deconstructed (plasma etching technique) and viewed with SEM.

The layers appear to be melted

PIXEL2016 - Sestri Levante



Damage evolution

Run	Good sensors on Inner Layer		Good sensors on Outer Layer		Comment
	installation	end of run	installation	end of run	
2014	100%	82%	100%	95%	LU damage, most of it in the first 15 days of operations
2015	99%	94%	98%	96% (93%)*	* = Lost control of an outer ladder (10 good sensors off)
2016	100%	95% (87%)+	99%	98%	⁺ = Current instability on inner ladder (8 good sensors off)

Good sensor = sensor with >95% active channels and uniform efficiency



PIXEL2016 - Sestri Levante



HFT Performance from 2014 data

DCA pointing resolution

- Design requirement exceeded: 46 µm for 750 MeV/c Kaons for the 2 sectors equipped with aluminum cables on inner layer
- \sim 30 µm for p > 1 GeV/c
- From 2015: all sectors equipped with aluminum cables on the inner layer

 $D^0 \rightarrow K \pi \text{ production}$ in $\sqrt{s_{NN}} = 200 \text{GeV} \text{Au} + \text{Au}$ collisions (First reconstruction of a small

Physics of D-meson productions

subsample)

- High significance signal
- Nuclear modification factor R_{AA}
- Collective flow v_2





Software/Firmware issues

Event decoder issue in 2014 data reconstruction

- A bug in the PXL hit decoding software led to an efficiency loss in the reconstructed 2014 Run data, affecting the preliminary STAR results
- After fixing the bug, the new data reconstruction and analysis showed a significant improvement in the performance, which now matches the simulation



- Readout firmware issue 2015 efficiency loss
 - A subtle bug introduced by a change in the PXL RDO firmware led to an efficiency loss in the 2015 Run data
 - The extensive tests with pattern data and the performance of full detector calibrations were inadequate to find this problem
 - A fast-offline tracking QA was put in place only after the 2015 Run
 - A post-run investigation based on external sensor illumination with LED allowed for firmware debugging and correction





Conclusions

- The first generation MAPS-based detector at a collider experiment successfully completed the 3-year physics program at RHIC
- As part of the Heavy Flavor Tracker, the PXL detector enabled STAR to perform a direct topological reconstruction of the charmed hadrons
- The 2013 Engineering Run was crucial for dealing with the unexpected problems that developed during the following physics data taking
- Due to beam-induced damage, the PXL construction phase continued throughout the entire detector life for yearly refurbishment and optimization
- The relatively short duration of the HFT program is not optimal to exploit such a complex detector system, nevertheless the project was successfully completed



Thank you for your attention!



