


CSC Operations

Indara Suarez (UCSB)
Mikhail Ignatenko (FNAL)
Evaldas Juska (TAMU)
Jian Wang (UF)

Run & DPG Coordination
Workshop, Turin
25.01.2017

Overview

- ME1/1 water cooling
- General status and problems faced during 2016
- Backgrounds and HV stability
- System improvements
- Plans for EYETS





ME1/1 water leak in late 2015

- **Water leak detected during Heavy Ion run of 2015**

- Leak traced to ME+1/1/13
- 3 chambers extracted, brought to the surface, cleaned and repaired


- **Precautionary measures**

- Enable water valve control of individual ME1/1 circuits when CMS is closed
- Humidity sensors installed in vacuum tank
- Water collectors installed to channel any water away from instrumented regions




ME1/1 cooling circuit repair


- The leak was caused by a faulty on-chamber cooling pipe joint
- Reinforcing all ME1/1 cooling joints during this YETS
 - High-performance rad-hard epoxy compound (Germetal)
 - Was shown to reliably seal the pipe joints even without any welding
 - Radiation tests at CHARM and CASTOR table showed no signs of degradation



Live channels



Number of dead CFEBs




- Readout efficiency $> 98.5\%$ at the end of 2016
- Main contributors to hardware problems
 - 2 CSCs without LV
 - Faulty connectors
 - 2 CSCs with dead ALCT
 - 5 dead DCFEBs due to faulty EEPROMs
 - 5 DCFEBs with dead optical links
 - Only 2 dead CFEBs in 2016
- Will recover what is accessible during this EYETS

DCFEB problems

- **Occasional data corruption due to monitoring (over JTAG)**
 - Disabled some of the monitoring on these boards (fixed)
 - We have lots of redundancy in monitoring, so this is not a problem
- **Loosing optical link (sometimes stops the run)**
 - Turns out to be caused by SEU in the optical transceiver module
 - Transmitter is being turned off
 - SEU probably triggers the laser safety mechanism
 - Implemented firmware to reset the transceivers on hard-reset
 - But could not deploy because of the EEPROM problem (below)
- **EEPROM problem**
 - Discovered when trying to update firmware in July and August 2016
 - 5 boards stopped working (only tried downloading to 60 / 504 boards)
 - Reason: cannot erase or write EEPROM
 - After the first erase readback is always corrupted
 - Current hypothesis is that this is caused by radiation
 - Previous radiation tests didn't show problems, but we did not try erase
 - Repeated radiation testing at CHARM (20kRad)
 - After irradiation, cannot erase these PROMs (Xilinx XCF128x)
 - Studies ongoing, alternatives are being tested for future DCFEBs


Overview

Lumi lost by categories





- Downtime contribution = ~2%
- Main cause -- SEUs
 - Corrupted data from the FPGAs
 - Some SEUs cause DCFEB optical transceivers to switch off
 - SEU mitigation
 - Hard-resets on-demand and periodically
 - Tripple modular redundancy in the firmware
 - Working on further improvements

Background



- CSC sees linear increase in background with increasing luminosity
- Small increase in background with 13TeV
- Magnetic field helps in inner rings
- During last EYETS rotating shielding was improved, but CSC doesn't see any noticeable effect in background rates




HV stability


- **Monitoring HV stability**

- Paying special attention during high lumi running
- So far very stable
- A few channels stay at lower than nominal voltage since run 1
- After lumi reached 10^{34} we started seeing these effects:
 - HV current spikes in a few ME1/3 chambers
 - Occasional malter effect on a few other chambers
 - We think these chambers can be trained

Malter effect in me+2/1/07






Spikes in HV currents of me-1/3/20



Gas gain equalization with HV tuning

- **Gas gain variation in CSC chambers was up to 3x**
 - Goal: equalize gas gains to achieve more uniform detector response
- **Tuned individual HV channel voltages to equalize gas gain**
 - The gas gain distribution now is impressively narrow
 - Note: this is average gas gain per sector, there is still variation within sectors
 - Recall: CSC has > 11000 HV channels/sectors
- **Next step: lower the gas gain on all chambers**
 - Maximize longevity
 - But preserve efficiency and good space resolution





Before HV corrections

After HV corrections

Trigger

- **EMTF has fully replaced CSCTF in 2016**
 - CSCTF was still in readout for offline cross-check studies
- **Chamber trigger timing is within a few ns**
- **Early EMTF firmware used the earliest LCT to form a trigger**
 - Later updated to choose the second earliest (like CSCTF)
 - This update reduced pre-firing rate from $\sim 2\%$ to $\sim 0\%$
- **So far RPC hits were not yet included in track finding algorithm**
 - In 2017 RPC hits will be included -- shown to improve efficiency




New OTMB firmware

- Many developments for improving efficiency in high PU
 - Individual improvements can be turned on/off in runtime
 - Extensively tested at GIF++
 - No problems seen, but improvements not visible due to small beam profile
 - Deployed at P5 on one chamber after pp run
 - No problems seen while running with or without algorithm improvements
 - Plan to deploy on a few crates during EYETS and later on the whole system
 - First run with the old algorithm and gradually turn on improvements


Simulation with PU = 50

CSC Trigger Stub Reconstruction CMS Simulation (PU50)




Simulation with PU = 140

CSC Trigger Stub Reconstruction CMS Simulation (PU140)




Online software

- SEU monitoring
 - Measurements saved to DB
- Improved firmware downloading stability
- EEPROM testing functions
- Support for new DCFEB and OTMB firmware functions



Total SEU count vs DCFEB position
Fills 5021 + 5024 = ~17 hours of beamtime



Only shows configuration memory SEUs

Single bit errors corrected automatically by the firmware

Plans for EYETS

- Reinforce ME1/1 water cooling joints
- Replace all dead DCFEBs
- DCFEB firmware update
 - Replace boards that show EEPROM problems during downloading
- Replace dead ALCTs
- Fix at least one broken LV connector (out of two)
 - May be possible to fix the second one as well
- Update ALCT slow control firmware
- Update OTMB firmware