### **Observations of Spontaneous Field Emission Occurrence with Subsequent Cavity Performance Degradation – or,**

### "What Just Happened?"

Joe Ozelis

Fermilab

TTC Meeting, 28 February - 2 March, 2011, Milan



Field emission (FE) has been with us since the beginning. Great strides have been made in eliminating or reducing it. Yet, it still occurs.

#### "Normal" FE Behavior (a "bad" cavity)

- Onset at some moderate field level
- Increases with increasing field
- Can lead to quench
- Can lead to low Q (Q-drop, FE loading)
- Increased radiation/dark current affects operation in CM

#### "Anomalous" FE behavior (a "good" cavity gone "bad")

- Onset typically at higher fields
- Sharp increase in radiation, to very high level
- Radiation remains active below original onset, in previously FE-free zones
- Q is decreased compared to non-FE performance
- Maximum field is lower



There have been 5 instances of this phenomenon observed during 9-cell cavity tests at Fermilab over the past ~20 months (55 tests). It is rare – 9% of the time.

- TB9ACC014 tested 5/1/2009
- TB9ACC006 tested 5/11/2009
- TB9ACC007 tested 11/6/2009
- TB9RI026 tested 4/26/2010
- TB9ACC015 tested 2/18/2011

Four of these cavities were subsequently re-processed and retested. TB9RI026 was re-processed and is in the test preparation queue, while TB9ACC015 is awaiting further activity.

# ₩ ТВ9АСС014







# TB9ACC014 – "Dejavu all over again"



# TB9ACC014 – "Dejavu all over again"



Plot of gradient/radiation vs time also clearly shows this change in FE behaviour.

Cavity was subsequently damaged (dent in cell #9), repaired (cell #9 de-tuned by ~20%), and re-tested. Quench limited (FE) to 30MV/m.

The cavity was then given additional HPR and re-tested... quench limited to 34MV/m, with some FE. No more "events".









**TB9ACC007** 











Optical inspections of TB9RI026 revealed a huge "crater" on the iris between cells 8/9, which got larger as EP was carried out.



**TB9ACC015** 





Next steps for TB9ACC015... optical inspection, then additional tumbling/EP...

Summary

Cavity	E <sub>FE Onset</sub> before event	E @ event	E <sub>FE Onset</sub> after event	E <sub>max</sub> after event	Next process	E <sub>FE Onset</sub> latest	E <sub>max</sub> latest
TB9ACC9014	25	25	16	28	HPR	35	38
TB9ACC9014 (part deux)	35	36	24	38	Tune, HPR	25	34
TB9ACC006	19	19	16	23	EP & HPR	29	32
TB9ACC007	19	33	16	25	HPR, EP & HPR	22	35
TB9RI026	22	29	15	20	Grind & EP		
TB9ACC015	20	32	9	25	Tumble & EP		

TTC Meeting, 28 February - 2 March, 2011, Milan



- In a handful of tests, FE "events" are observed that subsequently degrade cavity performance
  - It occurs without warning
  - It is not always accompanied by earlier FE
- It is suspected that "violent" emitters can "pollute" a cavity by spreading debris onto the surface of the cavity. If this debris lands on high field regions
  - FE onset may decrease
  - radiation may increase markedly
  - strong Q-drop or FE-induced quenches can occur
- Cavity performance can usually be recovered by additional processing steps
- Only (partial) avoidance technique is to not exceed "acceptance spec" when testing production cavities.