


# Fighting cold noise and early breakdown on the ATLAS ITk strips tracker

Sergio Diez Cornell (DESY) on behalf of the ATLAS ITk Strips community




## The Detector

- » The ATLAS Inner Tracker (ITk) will replace the current inner tracking detector in the HL-LHC phase to cope with the challenging conditions (occupancy, radiation, etc)
- » Tracker is an **all-silicon** detector with **pixel** and **strip** detectors arranged in a central barrel region and two **end-caps** in the forward regions




- » Main building blocks of the strips tracker are the **staves** and **petals** consisting of
  - Silicon microstrip detector **modules**: sensor with glued on readout and power electronics
  - Local support structures made out of carbon-based materials
  - Modules directly glued and wire bonded onto supports with low modulus, thermal adhesive




## Outstanding issues

- » Two standing issues surfaced on the verge of module production, with the very last pre-production version of components which we believe were mostly not present in earlier prototyping stages:
  - » **Cold noise**, discovered ~June 2022
  - » **Sensor cracking on loaded modules**, discovered ~ May 2023
- » Two taskforces were quickly formed within the ITk strips community and a huge effort has been devoted to understand and solve/mitigate both issues





## Cold Noise (CN) observations

- » **Clusters of noisy channels** observed at operating temperatures at/below -35C
- » Sometimes persisting even after returning to warm temperatures
- » Correlated with DC-DC power load
- » Correlated with glue locations under hybrids
- » Strong dependence on glue type:
  - » Big variations among electrical grade epoxies
  - » Thicker glue layers reduce magnitude
  - » Softer (not suitable) adhesives reduce or remove CN
- » **CN not present on Endcap modules**





## Sensor cracking

- » A fraction of sensors on pre-production staves had "early breakdown" below the 500V specification which was not present in module QC
- » Many modules were correctly attributed to humidity and static charge from handling tools
- » Further investigation found that some of these module had hard (<100V) breakdowns arising from **sensors fracturing when cycled to cold temperatures**
- » Most have high or low noise channels associated with the location of the crack
- » Cracks located near the power board, typically between hybrid and power board
- » Most didn't propagate to the sensor edges
- » **Affecting approx. 8-10% of modules loaded on supports**




## CN understanding

- » Further studies revealed that CN is in phase with DC-DC switching frequency (2MHz)
- » Able to emulate CN at room T with mechanical transducer
  - PB vibrates, mechanical waves couple to and travel along the sensor
- » Laser vibrometry helped identify the **noise source**:
  - » CN caused by **mechanical vibrations from capacitors on the power board** travelling through the sensor and inducing electrical noise
  - » Magnitude of vibrations on endcap modules is ~10x smaller
  - » Coupling mechanism - current theory under investigation: cooling causes hybrids to bend and glue to peel off under the hybrid edge, releasing charge
  - » Matches the observed Cold Noise behaviour






## CN status and mitigation

- » Identified most favourable adhesive and preparation treatment (Eccobond F112):
  - » **NO CN** on barrel Long Strip or endcap modules
  - » **Small amounts of CN** on short strip modules
  - » Impact on tracking and detector performance of Short Strips (SS) CN under evaluation
  - » **CN not a barrier to module production any more**




## Sensor cracking understanding & mitigations

- » Intense **thermo-mechanical simulation program**
  - » High stress regions coinciding with the observed crack formation regions
  - » **Guiding our mitigation efforts**
- » **Understanding of the effect**: peak stresses caused by bending of the electronics due to CTE mismatch, causing deformations on constrained sensors
- » Mitigations:
  - » **"Hysol" adhesive**: counter built-in stress by increasing stiffness at module-to-stave/petal joint
    - » Simulations: ~50% peak stress reduction
  - » **"Interposers"**: reduce stress region at the module level by decoupling mechanically electronics from sensor with intermediate polyimide layer
    - » Simulations: ~ 95% peak stress reduction
  - » **"Wide gap"**: spread stress region at the module level by increasing separation between electronic components
    - » Simulations: additional 10-20% stress reduction
- » Mechanical test program to **establish fracture stress** of sensors also in place
  - » Compatible with simulations, no effect from T, but long tail in the crack distribution



- » **Ongoing effort**: not a clear solution found yet
  - » Hysol staves/petals with nominal geometries still showing cracking signatures
  - » Hysol stave with wide gap modules **survived >50 cycles @ -45°C** without any cracks
  - » **Interposer modules showing promising results** (mechanical and electrical performance), no cold noise on SS interposed modules
- » **Path towards a working solution by Q4 2024**



## References

- G.I. Dyckes and M.G. Kurth on behalf of the ITk Strip collaboration, JINST 19, C04058 (2024)
- S. Diez on behalf of the ITk strips HV EB task force, ATLAS Open EB meeting (2024)



Frontier Detectors for Frontier Physics  
16<sup>th</sup> Pisa Meeting on Advanced Detectors  
May 26 – June 1 2024 • La Biodola, Isola d'Elba (Italy)