


# Map\_run6874




- M15-6 (131 in shoe) is working but T calibration coefficients are wrong (this crystal was unplugged last year due to tripping);


- M35-3 (308 in shoe) T sensor not working, but amplitude signals are properly read out.

- M32-9 (hardware num, 287 in shoe) sensor is working, but crystal was unplugged during the second round due to tripping;



Map\_run6874



Map\_run7029




T\_distr 6874

 $\Delta T$  (7029 - 6874)

T during physics run 7029: variation in  $T \approx 1^\circ\text{C}$  between calibration and physics runs  $\rightarrow$  once T calibration is fixed, expected variation in ADC response  $< 1\%$ .

C beam @ 200 MeV/u on 5 mm graphite, @ 120k events.  
 Trigger: margarita majority @ 5.  
 BM HV @ 1740 V.  
 Magnetic field ON.  
 Beam rate  $\sim 300\text{-}500$  Hz, configuration 24\_02.

>> During the second calibration round, no temperature was read out until run 6874.



>> Anomalous T decrease between run 6876 and 6874.

