

# Installation progress

Antonino Sergi


University of Birmingham

September 2014

## Installation: 3.5 days


- All HV cables: 1 damaged on 4 channels → replaced
- All LV cables: significant drop between PS and KTAG; sense wires?
- All DCS cables: improved robustness (2 full sets)
- DCS software: operational
- New signal PP: repaired and tested to be 100% fine
- All TDC cables: mostly tested
- HV boards: replaced those with broken channels
- Channel mapping: indubitably correct!
- Splitter boards: all tested (1 noisy channel)
- Heat sink: tested external NINO plate
- False floor: finished
- Noise: foreseen instability due to cables and connectors

# Splitter board



Just a bit flexible: we gave up for the stiffener

# False floor



## Prologue (June):

- LightBox 4 was tested and installed in June
- On the last day few HV boards were replaced for broken channels
- They were supposed to be tested at 100V to check for further broken channels

## Event (August):

- Installed boxes 7 and 8
- After solving DAQ issues we started looking for bad readout channels:
  - No noisy (digital) channels
  - Moved to DCS and switched on HV for box 6 → all ok
  - Switched on HV for boxes 1, 3, 4, 7, 8 → box 4 ramped up to 2500V
  - It took about 1 minute to realize it and switch it off

## Causal sequence:

- On the last day few HV boards were replaced for broken channels
- They were supposed to be tested at 100V to check for further broken channels
- One was somehow missed
- DCS doesn't show the actual setting from HV hardware, but the last setting transmitted
- DCS doesn't transmit settings for switch on command
- The last setting is actually stored on the HV board, rather than on the crate
- The HV board came back from the pool with a random setting
- This random setting (including all limits) was used when switched on

# HV accident: remarks


## Prevention:

- DCS should provide a "reset button" to set all parameters to reasonable values
- Every time a board is replaced it should be reset by pressing this button

## General:


- This DCS "feature" is common to all NA62 HV systems
- If any board is moved from a large HV detector to a small HV detector this kind of accident can happen again

# NINO plate






# NINO plate




# NINO plate




# NINO plate




# NINO plate




# NINO plate



# From The Book




# New lightboxes and secondary peaks



Lightbox 2 with NINO board 10


# New lightboxes and secondary peaks



PM66 (J52) extracted from lightbox and moved to small box




# New lightboxes and secondary peaks




Detached all other cables related to the mezzanine of PM66

# New lightboxes and secondary peaks




Lightbox 2 after replacing the NINO board (10 → 14)

# New lightboxes and secondary peaks




Lightbox 2 after replacing the NINO board (14  $\rightarrow$  15)

# New lightboxes and secondary peaks




Test of box 7 @115mV with few PMs using box 3 map NINO 14

# New lightboxes and secondary peaks




Back to box 2 after disconnecting PM43

# New lightboxes and secondary peaks




Detached all signal cables but those on mezzanine 6

# New lightboxes and secondary peaks



Detached all signal cables but those on mezzanine 7


# New lightboxes and secondary peaks



Moved cables from mezzanine 7 to 6




# New lightboxes and secondary peaks




Moved cables from mezzanine 1 to 6

# New lightboxes and secondary peaks




Moved cables from mezzanine 1 to 2

# New lightboxes and secondary peaks



Cross talk sum

# New lightboxes and secondary peaks



Replaced signal cables for mezzanine 6 with those from 1

# Understanding performance

## Current interpretation:

- Multiple peaks are triggered by cross-talk on the NINO board or mezzanine
- Peaks at time 0 can be hidden in the regular peak if all PMs are on
- Peaks at time  $> 0$  are the result of cross-talk reflection on the HV divider
- Cross-talk signal seems to be around 1-2% of the primary one
- Visible on NINO board mainly at low threshold (115mV)
- Apparently too small to be seen on oscilloscope
- Variation among LightBoxes due to a combination of different PM gain and different cross-talk on FE

## Future:

- We have a channel by channel scan of currently installed KTAG component (to be analysed)
- If it's more due to PM gain rather than NINO boards/mezzanines, it can be recovered adjusting HV
- It's verified that for R9880 NINO threshold doesn't affect efficiency

# Summary and Conclusions

- The installation went again pretty well (a part from the HV accident)
- Some trouble with the TEL62, but trivialities (that took 1 day to solve)
- LightBox 4 is back to Birmingham for post mortem analysis and resurrection
- Splitters are all available and tested (1 noisy channel to check)
- Cross talk can be an issue, but we have ways to define a working point that should be protected
- The option "NINO board out of the box" is tested and available at 0 cost
- One false floor plate to be cut (complaints for wheels)