

LIZETH MORALES GALLEGOS


# CAPACITY SALABORY


















## What do LQSs do?

QA/QC Quality assurance Quality control

We tell everyone there's some problem that has to be solved We also check stuff and register EVERYTHING



#### **IDENTIFICATION**



Originator's name:



If something is not as it should we snitch with an **NCR**Non Conformity Report

The more we know and add, the better!

## Control

### What to check?

#### **Stuff**



#### **Procedures**

		(IF INTEGRATED) DU UPI										DATE					58					
		Step 2. Pressure gauge																				
	Integration details available on DB	Measured underpressure				Underpressure at acceptance test Underpr						rpressure OK Underpressurere-done Exte					k ternal ly measured underpressure				т	
	[Y] [N]	bar				bar [Y]						[N] [Y] [N]						bar				Т
									Step 5	i. Collar												
ver.	Notes	Collar OK				MNOT OK, Pictures in drive:							Notes					Gel OK				-
		[Y] [N]															[Y] [N]			[7]		
					_			-	Step 7. (	Collectio	n Rings										_	Ī
ive:	Channel	0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	т
	Edge	-	_	-	-	_	-	-	_	-	-								-			۰
								$\overline{}$	-	-	-	-	-	-	-	-	-	-	-	-	-	+-
	Alignment								Se	ep 8. NC	8											
									Se	ep 8. NC	8	Step 2	Pressur	e gauge								
	Alignment	Man	nured us	ndarnra		Und	arorests.	re M Scr						e gauge		radona	fictor	nally me	anurad .	underno	attura.	
	Alignment  Integration details available on DB	Mea		nderpre	Bid.	Yos	ERISE.				Uhde	CPC & FRU	e OK	Vodes	Cessivite	re-done	Exter	nally me		underen	558408	
	Alignment	Mea		nderpre.	ELCR.	Ynd	erpress.	ge at acc	eptance	test		CPC & FRU		-	Cessivite	re-done	Exter	nally me	easured bar	underec	essuce.	I
	Alignment  Integration details available on DB			ar	Biot.		EDISE.	bar	eptance Step 5	e test	Uhde	CPC & FRU	e OK	<u>Vodes</u>	Cessivite		Exter	nally me			68/0	
·	Alignment Incegration details available on DB [V] [V]		b Collar O	ar	Best			bar	eptance Step 5	e test	Uhde	CPC & FRU	e OK	<u>Vodes</u>	) Cessifica		Exter	nally me	Gel OX			I
ŧ	Alignment Incegration details available on DB [V] [V]		b Collar O	er C	BIOL .			bar Picture	Step 5	e test	Unda (V	CPC & FRU	e OK	<u>Vodes</u>	) Cessifica		Exter		Gel OX			
	Alignment Incegration details available on DB [V] [V]		b Collar O	er C	BIGE.			bar Picture	Step 5	e test i. Collar	Unda (V	CPC & FRU	e OK	<u>Vodes</u>	) Cessifica		Exter		Gel OX			T
rit.	Alignment Integration details available on D8 (b) (N) Notes Channel Edge	M	Collar O	x (N)	BIGE.		NOT OK	bar Ficture	Step 5	e test i. Collar e: Collectio	Unda (V	SECRE	re OK N]	Unders (v	otes	N		D.	Gel OK	[N]		
	Alignment Integration details available on DB (V) (N) Notes Channel	M	Collar O	x (N)	Here.		NOT OK	bar Ficture	Step 5	e test i. Collar e: Collectio	Unda (V	SECRE	re OK N]	Unders (v	otes	N		D.	Gel OK	[N]		T

#### **Incidents**



## NCRS at CAPACITY

33.33% Opened

25.49% Waived

98.85% Repaired

51 NCRs since 2021

Registered in the DB



## Instrumentation

Everything that arrives to the lab should be registered.

If everything arrived ok, following the Procurement Responsibles instructions, we register in the DB

## Instrumentation

At the CAPACITY laboratory, even minor components or borrowed stuff is registered in a local inventory to keep track.

This simplifies the lives of the local Integration and Procurements teams as they are aware of all the consumables.

## Instrumentation

The CAPACITY lab is now the European storage site which means that many things arrive and many others have to be sent to other sites.

We keep track of "movement" with a Shipping Record Sheet (SRS). Everything is registered in the DB.

Important to warn your LQS about arrivals AND departures!

## SUMMARY

Keep your LQS close,
you never know when you'll
need her/him











Viale Carlo III 153, San Nicola la Strada (CE)



@km3netnapoli

