

Ecogas summary

G. Rigoletti



EP-DT
Detector Technologies

Shift report

- Logger crashed \Rightarrow script issue
- HFO bottle finished when logger crashed \Rightarrow no monitoring
- HFO bottle replaced
- Stability restarted
- Other logger crashes \Rightarrow DB intervention

