


Organization chart for UAr Production



Tasks and Responsibilities

INFN Responsibilities:

- Construction of the Urania Plant components.
- Shipping of the components to the Houston Warehouse.
- Sound Abatement, Supports for Piping & Air Coolers.
- Piping, Electrical & Instrument Interconnection.
- Leading the commissioning effort.

Princeton/Houston Responsibilities:

- Kinder Morgan Connection and Metering Station.
- Sitework for Argon Extraction Facility.
- Construction of Pre-Engineered Metal Building.
- Transportation of Urania plant to Colorado.
- Skids Rigging and Installation.
- HV Connection and Transformers.

Carleton Responsibilities:

- Cryogenic Liquid Transportation and Storage ISO Tanks.
- Shipment of argon to Sardinia and then to LNGS.
- Sampling System.

PNNL Responsibilities [PNNL LDRD]:

- LUAS Analysis System.

PNNL Scoping Study [DOE HEP]:

- Operations.

Fund sharing to be discussed by the RRB

