

What to show

- Stave assembled using the dummy modules w/ dummy chips;
- Modules measured with CMM: distributions of the distances between the markers, total length, etc;
- Positioning of the dummy modules: custom table w/ nominal values;
- After glueing: position of the markers w.r.t the nominal position;
- Planarity of the stave (cold plate): how it changes after:
 - BB to HB;
 - glueing the modules;
 - glueing to the spaceframe.