



# RPC EcoGas@GIF++ Collaboration Weekly Report

Dayron Ramos (University and INFN Bari)



# System status

- Weekly Source OFF scan ID: -
- Week stability run ID: [290](#), [291](#) (ongoing)
- HFO bottle ~ 1.6 kL used
- Humidity was high (around 6) → consequently regulated by reducing WET MFCs
- SHiP/LHCb chamber in stability (5kV) → high current after system restart
- EPDT chamber at 9kV



# Backup slides



# ScanID: