



Test on PMMA vessel

Gas Leakage

- The small leakage found on the HV flange was successfully fixed;
- The leakage of the “full” vessel is well below 1 cc/min



Overpressure

The optical window sagitta was tested as a function of the difference between internal and external pressure:

- up to 5.0 mbar a linear response was found

