



Operational Experience with the CDF Run II Silicon Detector




THE LEARNING OF EIGHT YEARS OF OPERATIONS

 The battle against corrosion in cooling lines and a remarkable repair



 The story of wirebond resonances and a protection system



And also...

- High automation of operations
- Ongoing maintenance
- Performance

Newer and future silicon detectors can make profit from these experiences